ARC FLASH HAZARD ALMETEK SIGNS & LABELS

Over 10 OSHA reportable Arch Flash related incidents occur everyday, several involving fatalities. Determining flash protection boundary and the appropriate PPE would be useless without the information being communicated effectively. Section 110.16 of the NEC 2002 code requires switchboards, panelboards, industrial control panels, and motor control centers to be field marked to warn personnel of the potential electric Arc Flash hazards. Clearly mark all equipment that present Arc Flash risk with Almetek's line of signs and pressure sensitive labels.



SAMPLE CUSTOM SIGNS/LABELS

A WARNING

ARCH FLASH / SHOCK HAZARD

PPE Level, 1 Layer 6 oz. Nomex Leather Gloves Faceshield

Restricted Approach - 500 V Class 00 G

80 VAC Shock Hazard when Cover is removed

Flash Hazard Boundary

2 inch Limited Approach 12 inch

cal/cm² Flash Hazard at 18

Almetek offers multiple OSHA & NFPA compliant Arc Flash Hazard labels and signs. Choose from Standard Printed and Fill-in styles, or fully customize your sign/label with specific PPE levels, company logos, colors, copy, size, images, etc. Call Customer Service today for more information, quotes or samples at 800-248-2080.

SAMPLE STANDARD SIGNS/LABELS A WARNING DANGER DANGER Arc Flash and Shock Hazard Arc Flash and Shock Hazard Arc Flash and Shock Hazard Appropriate PPE Required **Appropriate PPE Required** operate controls or open covers with iate personal protection equipment Appropriate PPE ailure to comply may result in injury or dea Required Refer to NFPA 70E for minimum PPE requ Refer to NFPA 70E for mi **A**WARNING ADANGER PELIGROA DANGER Arc Flash Riesgo de Arc Electrico Arc Flash and Shock Hazard Arc Flash Hazard **Appropriate PPE Required** Appropriate PPE Required opere mandos o biertas sin el equ Ŵ Appropriate PPE and Fit shirt Fit parts Fit coversite Fitsch suit || Hand hat || Pece ableta || Ear protect || Safety glas tools required when flure to comply m working on this equipment. A WARNING A WARNING Arc Flash and Shock Hazard Arc Flash and Shock Hazard **Appropriate PPE Required** Arc Flash & Shock Hazard Appropriate PPE Re Boundary Hazard at 18 inches calicm² Flas PPE Level ate controls or open covers ropriate personal protection Appropriate personal protection it in injury or equipment required Refer to NFPA 70E for r

A WARNING

Arc Flash Hazard

Appropriate PPE Required

FLASH PPE

DANGER

Arc Flash Hazard

Appropriate PPE Required

t in injury or

×.

te controis or open covers

to NFPA 70E for mi





2 Joy Drive • Hackettstown, NJ 07840 • 800-248-2080 • P: 908-850-9700 • www.almetek.com • csr@almetek.com

Arc Flash Hazard

Contractor Canada Congresso Ornata Ornata Ornata Diffust suit Diffust tood Diffust tood Diffust state Diffust unter Diffu